

USED ON


拓普联科

TOP-LINK

- #### 4. HARMFUL MATERIAL CONTROL FOLLOW "ROHS"

DIMENSIONS IN MM
TOLERANCES UNLESS
OTHER SPECIFIED

| | | |
|---|---|---|
| | | |
| 0 | 0 | 0 |
| 1 | 1 | 1 |
| 2 | 2 | 2 |
| 3 | 3 | 3 |
| 4 | 4 | 4 |
| 5 | 5 | 5 |
| 6 | 6 | 6 |
| 7 | 7 | 7 |
| 8 | 8 | 8 |
| 9 | 9 | 9 |

| | | | | | |
|------|------|---|---|-----|---|
| MATL | — | HT TR | — | FIN | — |
| DWN | APVD |  | | | |
| CHK | REL | | | | |

RECOMMEND SOLDER PADS
TOLERANCE = ±0.05

| | | | | | | | | | | | |
|-------------------|--|----------|--|------|--|------|--|--|--|---|--|
| L.D.C. | | REVISION | | APVD | | DATE | | 0 = $\pm 3^\circ$ 0.0 = $\pm 2^\circ$ | | REMOVE BURRS, BREAK SHARP EDGES R0.0 MAX DO NOT SCALE PRINT | |
| - TOLERANCE=0.005 | | | | | | | | | | | |
| DIST | | L.T.R. | | | | | | | | | |
| - | | | | | | | | | | | |