




DWG NO. C-200035



POINT OF MEASUREMENT — PICK&PLACE AREA






PICK&PLACE AREA




6. HARMFUL MATERIAL CONTROL FOLLOW "ROHS"

TOP-LINK



POINT OF MEASUREMENT

拓普联科



PAD OF PCB.

LOC		RECOMMEND PCB LAYOUT		0		= $\pm 3^\circ$	
-		TOLERANCE ± 0.05		0.0		= $\pm 1.5^\circ$	
DIST		L TR		REVISION RECORD		APVD DATE	
-						REMOVE BURRS, BREAK SHARP EDGES R0.0 MAX DO NOT SCALE PRINT	
		NAME		CUSTOMER DRAWING FOR 2, 2H, 0, 9W, ANTENNA CLIPS			
		SCALE		A4		DWG NO.	
		1:1		C-200035		SHEET 1 OF 1	
						REV A	

USED ON